



LEGEND

- Interior Wells (gauged only)
- ⊕ Interior Wells (gauged and sampled)
- Perimeter Wells (gauged and sampled)
- Piezometer (gauged only)
- Piezometer 4"
- ▲ Recovery wells (gauged only)
- ▨ Solid Waste Management Unit (SWMU) Area of Concern
- ⑤ Perimeter Segment Number

NOTE:

SEE FIGURES 2, 2A, 2B AND 2C FOR A COMPLETE REFERENCE TO WASTE MANAGEMENT UNITS (WMU) AND SURFACE IMPOUNDMENTS

NOT TO SCALE

GOLDEN EAGLE REFINERY MARTINEZ, CALIFORNIA	
WELL LOCATION MAP	
	FIGURE 6C